



Category SE	Repair Guidance	Ref. No. MME/R001/13	Page 1 of 1
Coverage <input type="checkbox"/> Distributor only <input checked="" type="checkbox"/> Please inform your dealers		Date Issued July 17, 2013	
Please convey this information to your <input type="checkbox"/> Director <input checked="" type="checkbox"/> General Manager <input checked="" type="checkbox"/> Warranty Dept. <input checked="" type="checkbox"/> Parts Dept. <input checked="" type="checkbox"/> Training Dept. <input checked="" type="checkbox"/> Field Rep.		Date Revised	
Applicable Models Mazda6; CX-5 fitted with forward sensing camera (FSC)		Applicable Countries or Specifications Europe	

Subject: Sensor aiming after windshield removal

PROBLEM DESCRIPTION

In MESI information is missing regarding necessity of Forward Sensing Camera (FSC) aiming after windshield removal in WINDSHIELD REMOVAL/INSTALLATION section.

COUNTERMEASURE

Please perform FSC aiming after windshield removal/replacement to ensure proper FSC operation. Aiming operation is described in MESI section BODY & ACCESSORIES / INSTRUMENTATION/ DRIVER INFO/ Forward Sensing Camera (FSC) aiming

MESI will be updated soon.

Customer Service Division
Mazda Motor Europe GmbH