

07:54 13MAR06 10:34 13MAR06

LINE OPCODE TECH TYPE HOURS

LIST NET TOTAL

A C/S NOISE IN FRONT END. TECH ORDERED SWAY BAR BUSHINGS.. PARTS HERE

CAUSE: EXCESSIVELY NOISY

R0402BRX STEBLIZER CONTROL LINK/BUSHING,R&R -BOTH

SIDES

33 WM 0.50

2 CC29-34-156A BUSH,STABILIZER-FRT

(L/C)

FC: PART#: COUNT:

CLAIM TYPE:

AUTH CODE:

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

5377 REPLACE FRONT SWAYBAR BUSHINGS, RD. TEST OK. NOTE" LINKS REPLACED
ON RO #41780, DATED 2/23/ 06, @ 3805 MILES. BUSHINGS NOT AVAILABLE AT
TH AT TIME. BUSHINGS ORDERED AND REPLACED TODAY.

B PERFORM MULTI-POINT INSPECTION

99P PERFORM MULTI-POINT INSPECTION

33 CM 0.00

0.00 0.00

BRKG Brake status "Green" Over 5mm (disc) or over

2mm (drum) remaining

33 CM 0.00

0.00 0.00

TIRG Tire status "Green" 7/32" or greater of

tread remaining

33 CM 0.00

0.00 0.00

BATTG INSPECT BATTERY CONDITION OK

33 CM 0.00

0.00 0.00

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

5380 ALL GREEN

C WASH CAR

NO CHARGE